





# HORN & STROBE CONNECTION



O2/CO2  
 99039, 99139, 99143, 99144



DIAGRAMS FOR 99016, 99029, 99129, 99028, 99145, 99097, 99141, 99035, 99128, 99020, 99045, UNLESS NOTED.